


# URUAV UR85HD

## Modifikationen



1. Kabelbinder um das Powerkabel zu sichern
2. WE WCAP-PTG5 100 $\mu$ F 25V (870 025 574 005) wegen [Oscar Liang -> Review: Crazybee F4 Pro Whoop FC \(V1 V2 V3 Changes\) -> Add Capacitor to Prevent FC Burnt Out](#)

## Meine Einstellungen

**DIFF** [ur85hd\\_my\\_settings\\_diff.txt](#)

**PID Quelle:** [Betaflight -> Betaflight Wiki -> Community Presets -> Brushed \ Brushless Whoop Class](#)

## Werkeinstellungen

**DIFF** [ur85hd\\_factory\\_settings\\_diff.txt](#)  
**DUMP** [ur85hd\\_factory\\_settings\\_dump.txt](#)

From:

<http://www.andreasgiemza.de/> - **Andreas' Wiki**

Permanent link:

[http://www.andreasgiemza.de/quadrocopter/uruav\\_ur85hd](http://www.andreasgiemza.de/quadrocopter/uruav_ur85hd)

Last update: **2019/09/05 17:43**

